

Car Visor Clip

Natasha Hatcher, Art/Egt 396
Repair Project



Visor with broken clip,
which happens to be on the
driver's side of the car. Not
good.



Not a good thing to have a visor
moving about when you are driving




Head on view of broken clip




Side view of broken clip




What the clip looked like before it was broken




Measurements




Initial start of model




Top view of clip



Bottom view of clip



Another clip being made



Different clips made